


Maglia di giunzione CWI

CWI Connecting link



Tipo Type	Portata WLL Kg	Dimensioni Dimensions							Peso Weight Kg
		b mm	c mm	d mm	e mm	g mm	s mm	t mm	
CWI 5-6	630	34	7	7	36	13	10	11	0,06
CWI 6-6	900	40	8	7	42	13	11	12	0,08
CWI 7-6	1250	51	9	9	54	17	13	14	0,14
CWI 8-6	1600	51	10	8,5	58	17	13	14	0,16
CWI 10-6	2500	70	13	13	73	25	18	18	0,37
CWI 13-6	4250	86	17	17	92	29	23	25	0,76
CWI 16-6	6300	105	21	20	104	37	32	28	1,41